

Acer Mobility Center Plug-In Release Notes

1. Product Release Information

Product Name: Acer Mobility Center Plug-In

Release Number: 3.0.3000

Release Date: December 7, 2007

Customer Support: Jones Hsu, White Wu and Erison Wu

2. Introduction

This document contains the release notes for Acer Mobility Center Plug-In. The following sections describe the release in detail and provide late-breaking or other information that supplements the main documentation.

3. What's New

- 3.0.3000, December 7, 2007
 - i. Change the launch path of Software Page tile for Gaia and eRecovery V3 spec. The launch path is "C:\Acer\Preload\Autorun\AutorunX\AutorunX.exe".
 - ii. Code reviewed by: Erison Wu

4. Minimum System Requirements

System Processor: Intel or AMD IA32 processor

System Memory: 512MB+

Free Disk Space: 10MB+

Operating System: Microsoft Windows Vista x86/x64

Networking: None required

Existing Software: .NET Framework 2.0

BIOS Support: ACPI-WMI specification v1.16

Port support: None

5. Installation and Upgrade Notes

- Installation
 - Run Acer Mobility Center Plug-In installer package to install all necessary binaries.
- Manifest
 - This release consists of the following items
 - i. Release Note
 - ii. Acer Mobility Center Plug-In

6. Version History

- 1.0.4301, November 28, 2007
 - iii. Support 28 multi-languages

- iv. Code reviewed by: Erison Wu
- 1.0.4300, September 11, 2007
 - v. MODIFY: MobilityService will handle OnShutdown event to fix unresponsive service issue.
 - vi. MODIFY: Bluetooth icon status will sync with the Bluetooth antenna status.
 - vii. Code reviewed by: Erison Wu
- 1.0.3003, November 24, 2006
 - viii. FIX: While Vista upgrade from home basic to home premium, the WMI control method will be cleared. Mobility Center Plug-In can not access WMI correctly.
 - ix. MODIFY: Change the icon of Share Folder tile when the sharing service is off.
 - x. Code reviewed by: Jay SJ Chang
- 1.0.3002, November 20, 2006
 - i. FIX: If user launch “Add New Device Wizard” dialog and then close Mobility Center, Acer Mobility Center Plug-In will not work when launching Mobility Center next time.
 - ii. Code reviewed by: Jay SJ Chang
- 1.0.3001, November 16, 2006
 - i. MODIFY: Revise “Bluetooth Off” icon and “Software Page” icon.
- 1.0.3000, November 10, 2006
 - i. FIX: Can not disable sharing service on some low-end platforms.
 - ii. FIX: Show the tiles very slow if there is no ETF.
 - iii. Remaining Issues
 - 1. Can not skip the first page of “Add New Device Wizard”.
- 1.0.2000, October 24, 2006
 - i. FIX: Add the detection of Bluetooth existence by WMI.
 - ii. FIX: Show “Software Page” tile only after installing Bluetooth Acer module driver.
 - iii. Remaining Issues
 - 1. Can not skip the first page of “Add New Device Wizard”.
- 1.0.1002, October 19, 2006
 - i. FIX: The icon of shared folder in Windows Explorer does not update immediately
 - ii. FIX: No function on x64 platform.
 - iii. FIX: Silent installation does not work.
 - iv. MODIFY: Change TcpChannel to IpcChannel for service.
 - v. Remaining Issues
 - 1. Can not skip the first page of “Add New Device Wizard”.
- 1.0.1001, October 11, 2006
 - i. FIX: Sharing permission is different between OS and Mobility center.
 - ii. Change order of “User Profile” and “My Computer” tab on Share Folder UI.
 - iii. Add multilingual support.
 - iv. Remaining Issues
 - 1. Can not skip the first page of “Add New Device Wizard”.
 - 2. The icon of shared folder in Windows Explorer does not update immediately.

- 1.0.1000, October 02, 2006
 - i. Add tab for exploring “My Document” directory on Share Folder UI.
 - ii. Remaining Issues
 - 1. Can not skip the first page of “Add New Device Wizard”.
 - 2. Sharing permission different between OS and Mobility center.
- 1.0.0001, September 25, 2006
 - i. Add the functions that launching “Add New Device Wizard” and “Bluetooth Devices” dialog for Bluetooth tile.
 - ii. Change Acer logo and Share Folder icon.
 - iii. Remaining Issues
 - 1. Can not skip the first page of “Add New Device Wizard”.
 - 2. Add tab for exploring “My Document” directory on Share Folder UI.
- 1.0.0000, August 31, 2006
 - i. First release
 - ii. Remaining Issues
 - 1. Functions of launch Bluetooth pairing and Bluetooth device center dialog are not ready