

## eNM Release Note

Version	Lang.	Release Date	Release note	Note
eNM Beta 2 v1.01.2.1  (Intel Wireless Driver: 9.0.3.9 Intel SDK: Muroc 10.0 Beta 2)	EN/TC/S  C/GE/SP/ IT/PO/FR	10/03/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ eNM main UI</li> <li>✧ eNM "Wireless manager" UI</li> <li>✧ eNM "Setting" UI</li> <li>✧ eNM "Advisor" UI</li> <li>✧ eNM "New profile wizard" UI</li> <li>✧ Status information in main UI</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧ Add a new UI named "Profile manager"</li> <li>✧ Add a new UI named "Network information"</li> <li>✧ Add a new UI named "Change Profile Name"</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ Help files - Only English</li> <li>✧ There are three items fail for CCX testing</li> <li>✧ The message ("Obtaining IP address. Please wait...") is English version for TC and SC language.</li> <li>✧ The word ("Rename") in profile manager page is too long for SP language.</li> <li>✧ The word ("Network Information") in advisor pager is too long for GER/SP/IT language.</li> </ul>	Please see the Installation guide for installing eNM
Version	Lang.	Release Date	Release note	Note
eNM Beta 2 v1.01.2.2  (Intel Wireless Driver: 9.0.3.9 Intel SDK: Muroc 10.0 Beta 2)	EN/TC/S  C/GE/SP/ IT/PO/FR	10/07/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧ 1. User can use space for naming profile name.</li> <li>✧ 2. AP list in main UI shows wrong wireless networks.</li> <li>✧ 3. The function of auto switch fails.</li> <li>✧ 4. LAN &amp; WLAN card adapter property settings fail for SC and SP language.</li> <li>✧ 5. The shortcut image of eNet management is wrong in 16-bit color depth.</li> <li>✧ 6. Channel information of WLAN shows incomplete in 120 dpi.</li> </ul>	Please see the Installation guide for installing eNM

			<ul style="list-style-type: none"> <li>✧ 7. The name of the last profile in profile manager shows strange symbol in 120 dpi.</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Access points stored in active profile will be shown in AP list if the access point is detected by system.</li> <li>✧ 2. The shared folder list in profile can be emptied.</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Support Intel PRO/Wireless 3945ABG WLAN card.</li> <li>✧ 2. The message ("Obtaining IP address. Please wait...") is ready for multi-language.</li> <li>✧ 3. The word ("Rename") in profile manager page is ready for multi-language.</li> <li>✧ 4. The word (Network Information") in advisor page is ready for multi-language.</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Help files - Only support English version.</li> <li>✧ 2. There is one item (5.1.10) fails for CCX testing.</li> <li>✧ 3. The message ("No supported WLAN card is detected. Please click "Yes" to install eNM...") is English version for other languages.</li> <li>✧ 4. The message ("Please configure the VPN connection first. Click "Ok" ...") is English version for other languages.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM Beta 2 v1.01.2.3 (Intel Wireless Driver: 9.0.3.9 Intel SDK: Muroc 10.0 PC1)	EN/TC/S C/GE/SP/ IT/PO/FR	10/11/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧ 1. The message ("No supported WLAN card is detected. Please click "Yes" to install eNM...") is ready for eight languages.</li> <li>✧ 2. The message ("Please configure the VPN connection first. Click "Ok" to ...") is English version for eight languages.</li> <li>✧</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Help files - Only support English version.</li> </ul>	
Version	Lang.	Release Date	Release note	Note

eNM RC 1 v1.01.3.1  (Intel Wireless Driver: 9.0.3.9 and 10.0.0120 Intel SDK: Muroc 10.0 PV1)	EN/TC/S  C/GE/SP/  IT/PO/FR	10/17/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧ 1. The image of VPN will be grayed if the VPN connection is creating.</li> <li>✧ 2. Network advisor page.</li> <li>✧ 3. The number of AP in profile exceeds the limitation (10).</li> <li>✧ 4. Ad hoc issues</li> <li>✧ 5. Show incorrect information of connected access point.</li> <li>✧ 6. CCX issue</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Take off the item "more and detail..." from the Switch profile column in menu of system tray.</li> <li>✧</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧ 1. The message ("Please select a wireless network") is ready for eight languages.</li> <li>✧ 2. eNM will pop up a warning message if user does not select any wireless network in Wireless Settings page during the process of profile creating.</li> <li>✧ 3. The message of current status will be shown in eNM main UI as user launches eNM main UI from eNM tray.</li> <li>✧ 4. New installation policy.</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Help files - Only support English version.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RC 1 v1.01.3.2  (Intel Wireless Driver: 9.0.3.9 and 10.0.0120 Intel SDK: Muroc 10.0 PV1)	EN/TC/S  C/GE/SP/  IT/PO/FR	10/24/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Windows Zero Config could not work correctly while disable Acer eNet Management</li> <li>✧ 2. Network advisor page.</li> <li>✧ 3. WiFi Network combo box appears two the same AP name. Save button invisible while connect another AP that never connect success.</li> <li>✧ 4. Endless auto switch while apply "Auto" profile.</li> <li>✧ 5. eNet Management UI show WLAN and LAN disconnected, but tray icon show Internet connected.</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Take off the profile icon from menu of system tray.</li> </ul>	

			<ul style="list-style-type: none"> <li>✧ 2. User does not do any modification while edit "Auto" profile, but "Change Profile Name" appears.</li> <li>✧ 3. eNM cannot find out WAN/LAN after install finished without restart system</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Help files are ready for eight languages.</li> <li>✧ 2. A warning message "It is recommended that you restart your computer for Acer eNet Management to function properly." is added. It is ready for eight languages.</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RC 2 v1.01.4.1  (Intel Wireless Driver: 9.0.3.9 and 10.0.0120 Intel SDK: Muroc 10.0 PV1)	EN/TC/S  C/GE/SP/  IT/PO/FR	11/2/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Help files.</li> <li>✧ 2. Crash of eNet Management.exe after renaming profile.</li> <li>✧ 3. Error message after start Main UI.</li> <li>✧ 4. Mystery of Button text Movement.</li> <li>✧ 5. LAN and Auto profile connected to WLAN, suspend and resume, no WLAN.</li> <li>✧ 6. Missing components of main UI after cancel during repair.</li> <li>✧ 7. Roaming issue.</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ 1. The wording "Basic" in "Setting" page change to "General"</li> <li>✧ 2. Moving the item "Network Information" in "Setting" page from Network to General.</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ CCX issue</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.000  (Intel Wireless Driver: 9.0.3.9 and 10.0.0120 Intel SDK: Muroc 10.0 PV1)	EN/TC/S  C/GE/SP/  IT/PO/FR	11/9/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Wrong resolution of application icon.</li> <li>✧ 2. The diagnosis button was not disabled during VPN connecting.</li> <li>✧ 3. The ambiguous type of access point.</li> <li>✧ 4. The malfunction of disable eNM item on tray menu.</li> </ul>	

			<ul style="list-style-type: none"> <li>✧ 5. Infinite connecting.</li> <li>✧ 6. Strange name of ISP during edit PPPoE.</li> <li>✧ 7. There is not show internet connected profile when mouse cursor move to tray icon on German UI.</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ 1. The maximum number of profile is limited to 24.</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧ 1. A warning message will be shown if the number of profile exceeds 24 as user wants to create a new profile.</li> <li>✧ 2. eNM will detect the IMVCM application during installation process.</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ CCX issue</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.001  (Intel Wireless Driver: 9.0.3.9 and 10.0.0120 Intel SDK: Muroc 10.0 PV1)	EN/TC/S  C/GE/SP/  IT/PO/FR	11/23/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Changing the images of "Advisor" and "Signal Strength".</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 20 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.002  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.7 Intel SDK: Muroc 10.1 TIC: 105796)	EN/TC/S  C/GE/SP/  IT/PO/FR	11/29/2005	<p><u>Fixed:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Refined:</u></p> <ul style="list-style-type: none"> <li>✧ 1. Changing Intel Muroc driver 10.0 PV1 to 10.1 PV2.</li> </ul> <p><u>Implemented:</u></p> <ul style="list-style-type: none"> <li>✧</li> </ul> <p><u>Know issues:</u></p> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 23 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note

# Release Notice



Acer Incorporated

eNM RTM v1.01.3.003  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.7 Intel SDK: Muroc 10.1 TIC: 105796)	EN/TC/S  C/GE/SP/  IT/PO/FR	12/05/2005	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧ 1. Changing images of signal strength and the position of AP list, signal strength, speed and connection status.</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 23 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.004  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.11 Intel SDK: Muroc 10.1 TIC: 106994)	EN/TC/S  C/GE/SP/  IT/PO/FR	12/16/2005	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧ 1. Change Intel WLAN card driver to 10.1.0.11.</li> <li>✧ 2. Change Intel Muroc SDK to 10.1.0.1 TIC: 106994.</li> <li>✧ 3. Change Intel Muroc API to 10.1.0.1 TIC: 106998</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 23 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.005  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.13 Intel SDK: Muroc 10.1 TIC: 107591)	EN/TC/S  C/GE/SP/  IT/PO/FR	12/23/2005	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧ 1. Change Intel WLAN card driver to 10.1.0.13.</li> <li>✧ 2. Change Intel Muroc SDK to 10.1.0.1 TIC: 107591.</li> <li>✧ 3. Change Intel Muroc API to 10.1.0.1 TIC: 107587</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 23 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release	Release note	Note

# Release Notice



Acer Incorporated

		Date		
eNM RTM v1.01.3.006  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.13 Intel SDK: Muroc 10.1 TIC: 107591)	EN/TC/S  C/GE/SP/  IT/PO/FR	01/17/2006	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧ Support Intel 3945BG WLAN card</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 23 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.007  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.13 Intel SDK: Muroc 10.1 TIC: 107591)	EN/TC/S  C/GE/SP/  IT/PO/FR	01/23/2006	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧ 1. eNM will hang up as user clicks the STOP button during the profile switching process.</li> <li>✧ 2. IP address does not be applied for Ad-hoc network.</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 23 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.008  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.11 Intel Muroc API 10.1 TIC: 106998)	EN/TC/S  C/GE/SP/  IT/PO/FR	02/07/2006	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧ 1. The preload process will hang up as installing eNM.</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧ 1. Change Intel WLAN card driver to 10.1.0.11.</li> <li>✧ 2. Change Intel Muroc SDK to 10.1.0.1 TIC: 106994.</li> <li>✧ 3. Change Intel Muroc API to 10.1.0.1 TIC: 106998</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – SSO and WMM (about 23 items) failed due the machine issue.</li> </ul>	
Version	Lang.	Release	Release note	Note

# Release Notice



Acer Incorporated

		Date		
eNM RTM v1.01.3.009  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.11 Intel Muroc API 10.1 TIC: 106998)	EN/TC/S  C/GE/SP/  IT/PO/FR	03/07/2006	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧ 1. eNet will detect the 3G software (Vodafone).</li> <li>✧</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – WMM failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.010  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.11 Intel Muroc API 10.1 TIC: 106998)	EN/TC/S  C/GE/SP/  IT/PO/FR	03/20/2006	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧ 1. eNet will detect the 3G software (Vodafone).</li> <li>✧</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧ CCX issue – WMM failed due the machine issue.</li> </ul>	
Version	Lang.	Release Date	Release note	Note
eNM RTM v1.01.3.011  (Intel Wireless Driver: 9.0.3.9 and 10.1.0.11 Intel Muroc API 10.1 TIC: 106998)	EN/TC/S  C/GE/SP/  IT/PO/FR	04/10/2006	<u>Fixed:</u> <ul style="list-style-type: none"> <li>✧ 1. CCX issue – WMM failed due the machine issue.</li> <li>✧ 2. Avoid Norton Antivirus altering warning message</li> </ul> <u>Refined:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Implemented:</u> <ul style="list-style-type: none"> <li>✧</li> </ul> <u>Know issues:</u> <ul style="list-style-type: none"> <li>✧</li> </ul>	