



## **BTW 5.1.0.4200**

### **Release Notes**

September 13, 2007

---

*Confidential and Proprietary Information*

---

© Broadcom Corp., 2007, All rights reserved.  
Printed in United States of America.  
16340 West Bernardo Drive  
San Diego, CA 92127  
Phone: (858) 385-8800  
Fax: (858) 385-8810

---

## LICENSED SOFTWARE

---

©200x Broadcom Corporation

©1999-2007 Broadcom Corporation

This program is the proprietary software of Broadcom Corporation and/or its licensors, and may only be used, duplicated, modified or distributed pursuant to the terms and conditions of a separate, written license agreement executed between you and Broadcom (an "Authorized License"). Except as set forth in an Authorized License, Broadcom grants no license (express or implied), right to use, or waiver of any kind with respect to the Software, and Broadcom expressly reserves all rights in and to the Software and all intellectual property rights therein. IF YOU HAVE NO AUTHORIZED LICENSE, THEN YOU HAVE NO RIGHT TO USE THIS SOFTWARE IN ANY WAY, AND SHOULD IMMEDIATELY NOTIFY BROADCOM AND DISCONTINUE ALL USE OF THE SOFTWARE.

Except as expressly set forth in the Authorized License,

1. This program, including its structure, sequence and organization, constitutes the valuable trade secrets of Broadcom, and you shall use all reasonable efforts to protect the confidentiality thereof, and to use this information only in connection with your use of Broadcom integrated circuit products.
2. TO THE MAXIMUM EXTENT PERMITTED BY LAW, THE SOFTWARE IS PROVIDED "AS IS" AND WITH ALL FAULTS AND BROADCOM MAKES NO PROMISES, REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE, WITH RESPECT TO THE SOFTWARE. BROADCOM SPECIFICALLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF TITLE, MERCHANTABILITY, NONINFRINGEMENT, FITNESS FOR A PARTICULAR PURPOSE, LACK OF VIRUSES, ACCURACY OR COMPLETENESS, QUIET ENJOYMENT, QUIET POSSESSION OR CORRESPONDENCE TO DESCRIPTION. YOU ASSUME THE ENTIRE RISK ARISING OUT OF USE OR PERFORMANCE OF THE SOFTWARE.
3. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL BROADCOM OR ITS LICENSORS BE LIABLE FOR (i) CONSEQUENTIAL, INCIDENTAL, SPECIAL, INDIRECT, OR EXEMPLARY DAMAGES WHATSOEVER ARISING OUT OF OR IN ANY WAY RELATING TO YOUR USE OF OR INABILITY TO USE THE SOFTWARE EVEN IF BROADCOM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES; OR (ii) ANY AMOUNT IN EXCESS OF THE AMOUNT ACTUALLY PAID FOR THE SOFTWARE ITSELF OR U.S. \$1, WHICHEVER IS GREATER. THESE LIMITATIONS SHALL APPLY NOTWITHSTANDING ANY FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY.

---

## INTRODUCTION

---

BTW requires Microsoft QFE 929577

**KNOWN ISSUE:**

HCRP, BPP and BIP-Print services do not work on Vista

Skype versions 3.2.0.163 and 3.2.0.175 both fail to switch the audio correctly in BTW. This is a Skype issue that they are aware of.

Printer Service cannot be Enabled for HCRP Server on Vista only

---

## CUSTOMER SUPPORT PORTAL (CSP)

---

Customers can submit enhancements, changes and/or defects against releases of software or firmware via the Broadcom Customer Support Portal (CSP). CSP cases are replicated into the Broadcom Bluetooth engineering change management database for review by the engineering community and change control boards.

If your project or program is not listed inside the CSP please contact your Broadcom representative whom can configure the CSP system for use with your unique needs.

To start using the CSP please visit <http://support.broadcom.com>.

## BTW 5.1.0.4200

---

### Resolved Defects

---

Critical

---

**ID(s):** BLTH00099807 **Subsystem:** BTConnectionWizard

**Version Found:** BTW\_PP\_05.01.00.39.00

**Headline:**

Message alignment issue when doing pairing in Denmark OS

**Release Note:**

The defect has been resolved

---

---

### Resolved Defects

---

Major

---

**ID(s):** BLTH00097294 CSP-109749 **Subsystem:** Unknown

**Version Found:** BTW\_PP\_05.01.00.37.00

**Headline:**

BTW5.1.0.3600 Headset device can be configured only once

**Release Note:**

After unpairing Headset device can be configured again

---

---

**ID(s):** BLTH00099989 **Subsystem:** Driver

**Version Found:** BTW\_PP\_05.01.00.41.00

**Headline:**

GKI buffer leak with role switch

**Release Note:**

Fixed buffer leak during role switch

---

---

**ID(s):** BLTH00100089 **Subsystem:** (UI) Bluetooth Neighborhood

**Version Found:** BTW\_PP\_05.01.00.41.00

**Headline:**

Explorer crashes when opens My Bluetooth Places

**Release Note:**

Explorer crash is fixed. It starts happen after installation of the all windows updates.

---

## BTW 5.1.0.4200

---

### Resolved Defects

---

Minor

**ID(s):** BLTH00099524

**Subsystem:** Unknown

**Version Found:** BTW\_PP\_06.00.01.53.00

**Headline:**

Error message after sending image via IE Send-To (BTW6.0.1.5300)

**Release Note:**

fixed crash in OBEX SDK callback protection

---

---

### Resolved Defects

---

Enhancements

**ID(s):** BLTH00099443

**Subsystem:** Other

**Version Found:** BTW\_PP\_05.01.00.40.00

**Headline:**

Update the Build and Release project in 5.1(change to copy the inf files)

**Release Note:**

A change has been made in the bat files for the drivers to copy the inf files during the build.

---

### **Pre-Installation Notices**

1. User must be logged on as administrator to install BTW. If non-administrative user is logged on and starts install, and then inputs administrator password, BTW will not install correctly.
2. Remote installation of BTW is not allowed. Remote install does not provide sufficient privileges for the unsigned driver install.
3. If the system is configured to share contacts between Outlook Express and Microsoft Outlook, Outlook Express will not be shown as one of the options for PIM Item Transfer for business cards.
4. Install Shield Developer Premier 10.5 is required to build the BTW Release.
5. When doing a clean install on Windows 98SE, you will need to use the inst.exe to install, not setup.exe.
6. If end user stops the DFU process in the middle of the DFU upgrade, the BT device will stay in DFU upgrade mode. This will prevent the user from using the BT mouse/keyboard and the user will need to use wired mouse/keyboard in order to restart the DFU and complete upgrade process. You will then be able to use Bluetooth mouse/keyboard again.
7. Prior to installing BTW: Open Windows Explorer -> Tools -> Folder Options -> Check box "Launch folder windows in separate process". This will ensure that the task bar is always visible.
8. Following an upgrade installation, all local services and client application will require secure authentication.

### **Post-Installation Notices**

1. If the client is set for NAP service, the Bluetooth Network adapter will not show that it is disconnected. Before using another Network access point, either reboot or manually renew the ip address.
2. Need to press OK in Control Panel/Sounds for MIDI files to play through headset. This is because Microsoft does not provide an API to set default MIDI device.
3. Volume level is set to maximum by default for Bluetooth Audio, once changed; it will retain its new setting.
4. Headset security uses the security of any headset shortcuts created.
5. In order to see traces in SpyLite, you will need to logoff of user account and log back in.
6. Some platforms cannot display the XP panel due to security setting for internet zones. For these platforms, the BT Neighborhood will switch to Classic View.

Create this registry entry:

[DWORD HKCU\Software\WIDCOMM\BTConfig\Debug\LogIPAddr = 0x7f000001](#)

Reboot.

### **BTW 5.1 Enhancements:**

- Hands Free Profile to provide HFP functions for VOIP applications like Skype.
- Integrate Skype APIs to use headset button presses to Answer/Terminate/Reject calls

## Installation Command Line Options

To install BTW from command line prompt or from a batch file, use the following command line options:

Setup.exe [/qn | /qb | /qr] [/nw] [/nodfu] [/L<LangId>] [/ru] [/ri]

/qn - Silent install without any UI and user interaction

/qb - Silent install with basic UI with progress dialog without any user interaction

/qr - Silent install with full UI without any user interaction

/nw- Setup.exe does not wait for BTW install to complete, exits after invoking MSI install.

/nodfu- Do not execute DFU during BTW install (even if configured for DFU in SvcPack.ini file)

/L -Installation language

<LangId> can be one of the following

1033: English

1046: Portuguese

1028: Chinese Tradition

2052: Chinese Simplified

1030: Danish

1043: Dutch

1035: Finnish

1036: French

1031: German

1040: Italian

1041: Japanese

1042: Korean

1044: Norwegian

1034: Spanish

1053: Swedish

1049: Russian

1045: Polish

/ru - Suppress reboot at the end of uninstall. (Relevant for Windows 98 and ME during upgrade)

/ri - Suppress reboot at the end of install (Relevant for Windows 98 and ME and if reboot is required on Windows 2000).

For example, to install silently without any UI in German language, use the following command line

setup.exe /qn /L1031

## Driver Versions

Driver	Description	Date	Version
btkrnl.inf	Bluetooth Bus Enumerator	9/4/2007	5.1.0.4100
btwusb.inf	Bluetooth Device Description	8/16/2007	5.1.0.4000
btport.inf	Bluetooth Communication Port	3/19/2007	5.1.0.3200
btwdndis.inf	Bluetooth LAN Access Server Driver	6/20/2007	5.1.0.3500
btwhidnt.inf	Bluetooth Remote Control	3/29/2007	5.1.0.3300
btaudio.inf	Bluetooth handsfree Audio and Stereo Audio	8/28/2007	5.1.0.4000