

Acer DX900 Patch (Fix SPN Flashing) Update Notification

Fix and Improvement

When using Hong Kong 3 SIM card in SIM1, the operator name is flashing

Required File:

CommunicationManager2.2.20.33.CAB

General Installation Steps:

- Copy the file into your device.
- Double click the file and follow the on-screen instruction.
- When the installation complete, please reset the device.