

Intel® SCO5 GbE Software Release 1 Gold
Issues Currently Under Investigation
11/08/02

Intel LAN Access Division

This document as well as the software described in it is furnished under license and may only be used or copied in accordance with the terms of the license. The information in this manual is furnished for informational use only, is subject to change without notice, and should not be construed as a commitment by Intel Corporation. Intel Corporation assumes no responsibility or liability for any errors or inaccuracies that may appear in this document or any software that may be provided in association with this document.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Except as permitted by such license, no part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means without the express written consent of Intel Corporation.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copyright © Intel Corporation 2002

*Third-party brands and names are the property of their respective owners.

Id	Priority	Title
20839	1	Gigabit UDP performance is poor due to OS limitations
20834	2	Gigabit performance with 82544 adapters is poor
21597	2	Heavy receive traffic will temporarily shut driver down
22932	2	Gigabit stress testing causes buildup of unreleased buffers (OS Limitation)
20947	2	Flow control cannot be turned off
22005	4	Configuration parameters do not generate error messages when invalid values are entered