

RevisionHistory

Doc No.															
Doc No.		Revision	Release date												
eNet_2.6.4009_EPTR		RV01	2007/9/5												
History															
Version	Issue date (Year/Month/Day)	Comment	Author												
2.6.4008	2007/5/2	First draft	Horace												
2.6.4008	2007/8/8	1. Remove "Compatibility-> Network and Sharing Center-> Printer sharing & Media sharing" 2. Modify Reliability: action when return from Sleep and Hibernate 3. Enrich the relationship between issue and test case	Cosmo												
		<table><tr><th>Issue</th><th>Test case</th></tr><tr><td>Proxy Bypass Setting Issue</td><td>Compatibility-> Software-dependent-> Bypass Proxy</td></tr></table>	Issue	Test case	Proxy Bypass Setting Issue	Compatibility-> Software-dependent-> Bypass Proxy									
Issue	Test case														
Proxy Bypass Setting Issue	Compatibility-> Software-dependent-> Bypass Proxy														
2.6.4008	2007/8/22	Enrich the relationship between issue and test case	Cosmo												
		<table><tr><th>Issue</th><th>Test case</th></tr><tr><td>Export profile to SD (bug#104)</td><td>Functionality-> Profile management-> Export-> Export to USB device</td></tr><tr><td>AP is re-connected automatically after clicking Disconnect (bug#097)</td><td>Reliability-> Switch user -> Admin01<->Admin02 -> Disconnect AP</td></tr><tr><td>eNet hangs issue (bug#096)</td><td>Reliability-> Switch user-> Admin01<->Admin02-> Continuously click "Disconnect" & "Connect"</td></tr><tr><td>No AP is found issue (bug#095)</td><td>Reliability->Switch user->Admin01<->Admin02->Wake up from Sleep mode</td></tr><tr><td>Connecting a WEP AP with the incorrect network key (bug#099)</td><td>Reliability-> Switch user -> Move location-> 9F to 15F</td></tr></table>	Issue	Test case	Export profile to SD (bug#104)	Functionality-> Profile management-> Export-> Export to USB device	AP is re-connected automatically after clicking Disconnect (bug#097)	Reliability-> Switch user -> Admin01<->Admin02 -> Disconnect AP	eNet hangs issue (bug#096)	Reliability-> Switch user-> Admin01<->Admin02-> Continuously click "Disconnect" & "Connect"	No AP is found issue (bug#095)	Reliability->Switch user->Admin01<->Admin02->Wake up from Sleep mode	Connecting a WEP AP with the incorrect network key (bug#099)	Reliability-> Switch user -> Move location-> 9F to 15F	
Issue	Test case														
Export profile to SD (bug#104)	Functionality-> Profile management-> Export-> Export to USB device														
AP is re-connected automatically after clicking Disconnect (bug#097)	Reliability-> Switch user -> Admin01<->Admin02 -> Disconnect AP														
eNet hangs issue (bug#096)	Reliability-> Switch user-> Admin01<->Admin02-> Continuously click "Disconnect" & "Connect"														
No AP is found issue (bug#095)	Reliability->Switch user->Admin01<->Admin02->Wake up from Sleep mode														
Connecting a WEP AP with the incorrect network key (bug#099)	Reliability-> Switch user -> Move location-> 9F to 15F														





RevisionHistory

		Fail to connect APs after moving (bug#098)	Reliability -> Switch user -> Move location-> 9F to 12F	
2.6.4008	2007/8/24	Enrich the relationship between issue and		Cosmo
		Issue	Test case	
		eNet is in disconnected state when first launch ETF (bug#108)	Functionality-> UI-> Amazing icon	

Preparation

Schedule		
Item	Result	Remark
Owner	Cosmo Chien	
Reviewer		
Period (Expected)	2007/8/31~2007/9/5	
Period (Practical)	2007/8/31~2007/9/5	
Priority selection		
Item	Result	Remark
P2	A	Please fill "A or B"
Check the devices are testable		
Item	Result	Remark
Hardware-dependent		
WMI	Pass	
INT15	Pass	
Software-dependent		
eAPs		
Silent install in Audit	Pass	Essential
Enable logs	Pass	Essential
Norton Internet Security	10.1.0.26	Essential
NTI CD/DVD Maker	7.7.0.2508	Essential
CyberLink PowerDVD	7.3	
Adobe Reader	8.1.0.0	
Yahoo Toolbar	6.5.0.0	
Windows Office	N/A	
Sun Java	N/A	
NTI Home Video Marker	N/A	
CyberLink Power Producer	N/A	
Webaroo toolbar	N/A	
Related document		
Item	Result	Remark
Before testing		
需求追溯表	Pass	
Build notes	Pass	
Release notes	Pass	
After testing		
Test scope		Check actually to update
Environment		
Item	Result	Remark
System environment		
Notebook platform	Pantanal-49	
CPU	Intel Core 2 Duo CPU T7300 @ 2.00GHz	
RAM	2GB	
BIOS		
OS	Windows Vista Business	

Preparation

Installed programs	 Installed_programs		Paste "Control Panel- >Programs and Features / Add or Remove Programs"
eAP version	 eAP_version		Paste "eAP tool-bar->About"
Notebook platform	Chapala-10		x64 platform
CPU	Intel Core 2 Duo CPU T7300 @ 2.00GHz		
RAM	1GB		
BIOS	v1.3704		
OS	Windows Vista Business		
Installed programs	 Installed_programs		Paste "Control Panel- >Programs and Features / Add or Remove Programs"
eAP version	 eAP_version		Paste "eAP tool-bar->About"

BugSummary

[illegible]

Functionality

Priority	Item	Remark	Pass / Fail
	Install/uninstall		
	Upgrade program		
2-A	ETF is closed first		Pass
1	ETF is not closed first		Pass
	Install program		
	Silent install		
1	General		Pass
2-A	The same version exists		Pass
	Manual install		
2-A	ETF is closed first		Pass
1	ETF is not closed first		Pass
	Execute multiple installations		
	Uninstall program		
2-A	ETF is closed first		Pass
1	ETF is not closed first		Pass
	Profile management		
	Auto		
	Create		
2-A	General		Pass
	Delete		

Functionality

1	General		Pass
1	Delete "Auto"		Pass
	Edit		
2-A	General	- Profile settings cases: Functionality- >Profile Settings	Pass
1	Edit the profile in use	- Profile settings cases: Functionality- >Profile Settings	Pass
	Rename		
	Export		
1	Export to USB device	- Added according to bug#104	Pass
	Import		
	File corruption		
	Profile settings		
	WLAN Settings		
	Internet		
	Filewall		
	Internet		
	Enable		
	PPPoE		
	Enable		
	Shared Folders		
	Printer and Programs		
	Wireless association		
	Security setting		
	eNet settings		
	General		
	Launch when starting		
	Profile switching		
	Automatic switching		
	Network		
	UI		
	Network advisor		

Functionality

	Main		
	Diagnostic tools		
	Launch/exit program		
	Launch		
1	From tool-bar		Pass
1	From "Start Menu"		Pass
1	From "Tray icon"		Pass
1	Exit		Pass
1	Amazing icon	- Add on 2.6.4008 according to bug#108	Pass
	Hardware button		

Compatibility

Priority	Item	Remark	Pass / Fail
	Software-dependent		
	Device Manager		
	WLAN driver		
2-A	Disable		Pass
	LAN driver		
1	Disable	- The case could be implemented by ePower CableSense function	Pass
1	Enable	- The case could be implemented by ePower CableSense function	Pass
	Network and Sharing Center		
	Manage wireless network		
	Sharing and Discovery		
	Password protected sharing		
	Public folder sharing		
	File sharing		
	Manage the profile		
1	Connect to a network		Skip
	Bypass Proxy Server		
1	Apply profile setting	- Add on 2.6.4008 according to bug#107	Pass

Compatibility

1	Change IE proxy setting	- Add on 2.6.4008 according to bug#107	Pass
	Hardware-dependent		
	WLAN		
1	Intel	- Should collect and define "releated functions"	Pass
1	Broadcom	- Should collect and define "releated functions"	Skip
1	Atheros	- Should collect and define "releated functions"	Skip
	LAN		
1	Broadcom		Pass
1	Non-Broadcom		Pass

Performance

Priority	Item	Remark	Pass / Fail
	Light loading (After restarting the test device)		
	Heavy loading		

Reliability

Priority	Item	Remark	Pass / Fail
	Power mode (S3/S4)		
	Sleep		
	Enable "Switch... automatically"		
	Static		
2-A	On battery		Pass
	Dynamic		
2-A	On battery->Sleep- >Plugged in		Pass
	Disable "Switch... automatically"		
	Static		
2-A	On battery		Pass
	Dynamic		

Reliability

2-A	On battery->Sleep->Plugged in		Pass
	Hibernate		
	Enable "Switch... automatically"		
	Static		
2-A	On battery		Pass
	Dynamic		
2-A	On battery->Sleep->Plugged in		Pass
	Disable "Switch... automatically"		
	Static		

Reliability

2-A	On battery		Pass
	Dynamic		
2-A	On battery->Sleep->Plugged in		Pass
	Switch user		
	Admin01<->Admin02		
2-A	Profile management		Pass
1	Disconnect AP	- Added according to bug#097	Pass

Reliability

1	Continuously click "Disconnect" & "Connect"	- Added according to bug#096	Pass
	Wake up from Sleep mode	- Added according to bug#095	Pass
	LAN environment		
2-A	Different		Pass
	WLAN environment		
1	The same		Pass
1	Different		Pass
	Admin<->Standard		

Reliability

2-A	Profile management		Pass
	LAN environment		
2-A	The same		Pass
	WLAN environment		
2-A	The same		Pass
	Admin<->Guest		
	Standard<->Guest		
	Move location		
1	9F to 15F	- Added according to bug#099	Pass

Reliability

1	9F to 12F	- Added according to bug#098	Skip
	Long-time test		
1	Sleep		Skip
1	Hibernate		Skip
1	Restart		Skip

Regression

Those changed in this release	Possible effect (Items to be tested further)	Test result from PA (Pass / Fail)
Issues solved		
(0107) "Bypass proxy server for local address" and "Exceptions" proxy setting will be wrong after apply eNet profile with proxy setting	Set IE proxy settings	Pass
	Remove IE proxy settings	Pass
eNet may get wrong WLAN status as virtual WLAN NIC is installed	Install Swisscom 3G software and launch eNet	Pass
	Install OfficeScan's filter driver and launch eNet	Pass
Spec changes		
Remove function for detecting 3G software	Install	Pass
	Launche eNet first and launch 3G software	Pass
	Launche 3G software first and launch eNet	Pass

Priority	Item	Remark	Pass / Fail
	3G software		
	Vodafone Mobile Connect		
	Launch	- Add on 2.6.4009 based on spec. change - Only test when 3G device exists	
	Connect / Disconnect	- Add on 2.6.4009 based on spec. change - Only test when 3G device exists	
	Switch profile	- Add on 2.6.4009 based on spec. change - Only test when 3G device exists	
	Swisscom UDM		
	Launch	- Add on 2.6.4009 based on spec. change - Only test when 3G device exists	
	Connect / Disconnect	- Add on 2.6.4009 based on spec. change - Only test when 3G device exists	
	Switch profile	- Add on 2.6.4009 based on spec. change - Only test when 3G device exists	