



BTW 6.0.1.6400

Release Notes

April 30, 2008

Confidential and Proprietary Information

© Broadcom Corp., 2008, All rights reserved.
Printed in United States of America.
16340 West Bernardo Drive
San Diego, CA 92127
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

©200x Broadcom Corporation

This program is the proprietary software of Broadcom Corporation and/or its licensors, and may only be used, duplicated, modified or distributed pursuant to the terms and conditions of a separate, written license agreement executed between you and Broadcom (an "Authorized License"). Except as set forth in an Authorized License, Broadcom grants no license (express or implied), right to use, or waiver of any kind with respect to the Software, and Broadcom expressly reserves all rights in and to the Software and all intellectual property rights therein. IF YOU HAVE NO AUTHORIZED LICENSE, THEN YOU HAVE NO RIGHT TO USE THIS SOFTWARE IN ANY WAY, AND SHOULD IMMEDIATELY NOTIFY BROADCOM AND DISCONTINUE ALL USE OF THE SOFTWARE.

Except as expressly set forth in the Authorized License,

1. This program, including its structure, sequence and organization, constitutes the valuable trade secrets of Broadcom, and you shall use all reasonable efforts to protect the confidentiality thereof, and to use this information only in connection with your use of Broadcom integrated circuit products.
2. TO THE MAXIMUM EXTENT PERMITTED BY LAW, THE SOFTWARE IS PROVIDED "AS IS" AND WITH ALL FAULTS AND BROADCOM MAKES NO PROMISES, REPRESENTATIONS OR WARRANTIES, EITHER EXPRESS, IMPLIED, STATUTORY, OR OTHERWISE, WITH RESPECT TO THE SOFTWARE. BROADCOM SPECIFICALLY DISCLAIMS ANY AND ALL IMPLIED WARRANTIES OF TITLE, MERCHANTABILITY, NONINFRINGEMENT, FITNESS FOR A PARTICULAR PURPOSE, LACK OF VIRUSES, ACCURACY OR COMPLETENESS, QUIET ENJOYMENT, QUIET POSSESSION OR CORRESPONDENCE TO DESCRIPTION. YOU ASSUME THE ENTIRE RISK ARISING OUT OF USE OR PERFORMANCE OF THE SOFTWARE.
3. TO THE MAXIMUM EXTENT PERMITTED BY LAW, IN NO EVENT SHALL BROADCOM OR ITS LICENSORS BE LIABLE FOR (i) CONSEQUENTIAL, INCIDENTAL, SPECIAL, INDIRECT, OR EXEMPLARY DAMAGES WHATSOEVER ARISING OUT OF OR IN ANY WAY RELATING TO YOUR USE OF OR INABILITY TO USE THE SOFTWARE EVEN IF BROADCOM HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES; OR (ii) ANY AMOUNT IN EXCESS OF THE AMOUNT ACTUALLY PAID FOR THE SOFTWARE ITSELF OR U.S. \$1, WHICHEVER IS GREATER. THESE LIMITATIONS SHALL APPLY NOTWITHSTANDING ANY FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY.

INTRODUCTION

BTW requires Microsoft QFE 929577

Known Issue: Skype versions 3.2.0.163 and 3.2.0.175 both fail to switch the audio correctly in BTW.

CUSTOMER SUPPORT PORTAL (CSP)

Customers can submit enhancements, changes and/or defects against releases of software or firmware via the Broadcom Customer Support Portal (CSP). CSP cases are replicated into the Broadcom Bluetooth engineering change management database for review by the engineering community and change control boards.

If your project or program is not listed inside the CSP please contact your Broadcom representative whom can configure the CSP system for use with your unique needs.

To start using the CSP please visit <http://support.broadcom.com>.

BTW 6.0.1.6400

Resolved Defects

Critical

ID(s): BLTH00123218

Subsystem: Unknown

Headline:

SendTo does not recover after terminated from the server side

Release Note:

Fixed a problem in OPP that it does not accept files after PIM is disabled/enabled.

Resolved Defects

Major

ID(s): BLTH00123918

Subsystem: Shell Extension

Headline:

Send Chinese web page via Bluetooth failed

Release Note:

IE Send via Bluetooth handles non-English character set in web page correctly.

ID(s): BLTH00126384

Subsystem: Installation

Headline:

Installer errors that OS is not Vista when installing on Vista

Release Note:

Use manifest file to declare the installer as compatible with Vista

Resolved Defects		Enhancements
<hr/>		
ID(s):	BLTH00120034	Subsystem: Tools
Headline:		
update driver build procedures to point to new gera fileserver		
 Release Note:		
Internal tool change, no customer release note.		
<hr/>		

Installation Command Line Options

To install BTW from command line prompt or from a batch file, use the following command line options:

Setup.exe [/qn | /qb | /qr] [/nw] [/nodfu] [/L<LangId>] [/ru] [/ri]

/qn - Silent install without any UI and user interaction

/qb - Silent install with basic UI with progress dialog without any user interaction

/qr - Silent install with full UI without any user interaction

/nw- Setup.exe does not wait for BTW install to complete, exits after invoking MSI install.

/nodfu- Do not execute DFU during BTW install (even if configured for DFU in SvcPack.ini file)

/L -Installation language

<LangId> can be one of the following

1033: English

1046: Portuguese

1028: Chinese Tradition

2052: Chinese Simplified

1030: Danish

1043: Dutch

1035: Finnish

1036: French

1031: German

1040: Italian

1041: Japanese

1042: Korean

1044: Norwegian

1034: Spanish

1053: Swedish

1049: Russian

1045: Polish

/ru - Suppress reboot at the end of uninstall. (Relevant for Windows 98 and ME during upgrade)

/ri - Suppress reboot at the end of install (Relevant for Windows 98 and ME and if reboot is required on Windows 2000).

For example, to install silently without any UI in German language, use the following command line

setup.exe /qn /L1031

Pre-Installation Notices

1. User must be logged on as administrator to install BTW. If non-administrative user is logged on and starts install, and then inputs administrator password, BTW will not install correctly.
2. If the system is configured to share contacts between Outlook Express and Microsoft Outlook, Outlook Express will not be shown as one of the options for PIM Item Transfer for business cards.
3. Install Shield Developer Premier 10.5 is required to build the BTW Release.
4. If end user stops the DFU process in the middle of the DFU upgrade, the BT device will stay in DFU upgrade mode. This will prevent the user from using the BT mouse/keyboard and the user will need to use wired mouse/keyboard in order to restart the DFU and complete upgrade process. You will then be able to use Bluetooth mouse/keyboard again.
5. Prior to installing BTW: Open Windows Explorer -> Tools -> Folder Options -> Check box "Launch folder windows in separate process". This will ensure that the task bar is always visible.

Post-Installation Notices

1. Volume level is set to maximum by default for Bluetooth Audio, once changed; it will retain its new setting.
2. In order to see traces in SpyLite, you will need to logoff of user account and log back in.

Create this registry entry:

[DWORD HKCU\Software\WIDCOMM\BTConfig\Debug\LogIPAddr = 0x7f000001](#)

Reboot.