



Release Notes

BTW 5.1.0.3300

April 05, 2007

Confidential and Proprietary Information

© Broadcom Corp., 2004, All rights reserved.
Printed in United States of America.
15435 Innovation Drive
San Diego, CA 92128
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

© Copyright 2004, Broadcom® Corporation ("Broadcom"). All rights reserved.

WARNING:

This software and accompanying documentation are protected by copyright law and international treaties. Unauthorized reproduction or distribution of this software, or any portion of it, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under the law.

Use of this software is governed by the terms of the end user license agreement that accompanies or is included with such software. Unless otherwise noted in the end user license agreement, or herein, no part of the documentation accompanying this software, whether provided in printed or electronic form may be reproduced in any form, or stored in a database or retrieval system, or transmitted in any form or by any means, or used to make any derivative work (such as translation, transformation, or adaptation) without the express, prior written consent of Broadcom.

Trademarks

Broadcom® and the pulse logo are trademarks of Broadcom Corporation and/or its subsidiaries in the United States and certain other countries. Microsoft® and Windows® are trademarks of Microsoft Corporation. Bluetooth® is a trademark of the Bluetooth SIG. Any other trademarks mentioned are the property of their respective owners.

Issues addressed in BTW 5.1.0.3300

BLTH00080094

SendTo Explorer device selection does not have icon for Headset device

Release Note:

SendTo Explorer device selection does have icon for Headset device

BLTH00082505

Cannot send JPG files using BIP

Release Note:

the defect has been resolved

BLTH00082526

signing error in build

Release Note:

Fixed build error

BLTH00082643

Additional sanity checks to prevent RFCOMM Bluescreen

Release Note:

Added additional checks in the processing of the RFCOMM messages to prevent Bluescreen

BLTH00082951

Failed to connect HID mouse (from David Liu)

Release Note:

The bug in the HID driver was blocking L2CAP connection request for the interrupt channel. As a result BTStackServer was detecting failure even when HID installation was successful.

BLTH00082969

AVRCP actions are repeated when iTunes is in the background

Release Note:

New version of iTunes does not need multimedia hook function.

BLTH00083040

BTW 5.1, File and folder names from Japanese language do no display correctly on English OS

Release Note:

If remote files folders in FTP have Asian characters, they will be displayed correctly on English OS

BLTH00083134

Merge Cr <scm-bmt-autobuilder>

Release Note:
Merge Cr

BLTH00083283

btw5.1 after new install, can not make any rfcomm connections on Vista

Release Note:

On Vista, start the initial setup wizard in user context

Pre-Installation Notices

1. User must be logged on as administrator to install BTW. If non-administrative user is logged on and starts install, and then inputs administrator password, BTW will not install correctly.
2. Remote installation of BTW is not allowed. Remote install does not provide sufficient privileges for the unsigned driver install.
3. If the system is configured to share contacts between Outlook Express and Microsoft Outlook, Outlook Express will not be shown as one of the options for PIM Item Transfer for business cards.
4. Install Shield Developer Premier 10.5 is required to build the BTW Release.
5. When doing a clean install on Windows 98SE, you will need to use the inst.exe to install, not setup.exe.
6. If end user stops the DFU process in the middle of the DFU upgrade, the BT device will stay in DFU upgrade mode. This will prevent the user from using the BT mouse/keyboard and the user will need to use wired mouse/keyboard in order to restart the DFU and complete upgrade process. You will then be able to use Bluetooth mouse/keyboard again.
7. Prior to installing BTW: Open Windows Explorer -> Tools -> Folder Options -> Check box "Launch folder windows in separate process". This will ensure that the task bar is always visible.
8. Following an upgrade installation, all local services and client application will require secure authentication.

Post-Installation Notices

1. If the client is set for NAP service, the Bluetooth Network adapter will not show that it is disconnected. Before using another Network access point, either reboot or manually renew the ip address.
2. Need to press OK in Control Panel/Sounds for MIDI files to play through headset. This is because Microsoft does not provide an API to set default MIDI device.
3. Volume level is set to maximum by default for Bluetooth Audio, once changed; it will retain its new setting.
4. Headset security uses the security of any headset shortcuts created.
5. In order to see traces in SpyLite, you will need to logoff of user account and log back in.
6. Some platforms cannot display the XP panel due to security setting for internet zones. For these platforms, the BT Neighborhood will switch to Classic View.

Create this registry entry:

[DWORD HKCU\Software\WIDCOMM\BTConfig\Debug\LogIPAddr = 0x7f000001](#)

Reboot.

BTW 5.1 Enhancements:

- Hands Free Profile to provide HFP functions for VOIP applications like Skype.
- Integrate Skype APIs to use headset button presses to Answer/Terminate/Reject calls

BTW 5.1 (LE) Version Limitations:

- The AV profiles (GAVDP, AVRCP, and A2DP) are disabled.
- The data rate is limited to Basic Rate only.

Installation Command Line Options

To install BTW from command line prompt or from a batch file, use the following command line options:

Setup.exe [/qn | /qb | /qr] [/nw] [/nodfu] [/L<LangId>] [/ru] [/ri]

/qn - Silent install without any UI and user interaction

/qb - Silent install with basic UI with progress dialog without any user interaction

/qr - Silent install with full UI without any user interaction

/nw- Setup.exe does not wait for BTW install to complete, exits after invoking MSI install.

/nodfu- Do not execute DFU during BTW install (even if configured for DFU in SvcPack.ini file)

/L -Installation language

<LangId> can be one of the following

1033: English

1046: Portuguese

1028: Chinese Tradition

2052: Chinese Simplified

1030: Danish

1043: Dutch

1035: Finnish

1036: French

1031: German

1040: Italian

1041: Japanese

1042: Korean

1044: Norwegian

1034: Spanish

1053: Swedish

1049: Russian

1045: Polish

/ru - Suppress reboot at the end of uninstall. (Relevant for Windows 98 and ME during upgrade)

/ri - Suppress reboot at the end of install (Relevant for Windows 98 and ME and if reboot is required on Windows 2000).

For example, to install silently without any UI in German language, use the following command line

setup.exe /qn /L1031

Driver Versions

Driver	Description	Date	Version
btkrnl.inf	Bluetooth Bus Enumerator	3/29/2007	5.1.0.3300
btwusb.inf	Bluetooth Device Description	3/19/2007	5.1.0.3200
btport.inf	Bluetooth Communication Port	3/19/2007	5.1.0.3200
btwdndis.inf	Bluetooth LAN Access Server Driver	10/3/2006	5.1.0.2400
btwhidnt.inf	Bluetooth Remote Control	3/29/2007	5.1.0.3300
btaudio.inf	Bluetooth handsfree Audio and Stereo Audio	3/19/2007	5.1.0.3200