

October 20, 2010

Greetings,

BroadSoft is pleased to announce that the Yealink SIP TxP Series has been formally validated with BroadWorks. The device model(s) listed below have been validated as interoperable with the BroadWorks SIP interface. Any issues and limitations identified during the interoperability testing are documented in the BroadSoft Partner Configuration Guide (PCG) *PartnerConfigGuide Yealink SIP TxP*. The PCG is available to BroadSoft customers on the BroadSoft Xchange website, <a href="http://xchange.broadsoft.com">http://xchange.broadsoft.com</a>.

BroadSoft validates that the device works properly with the BroadWorks SIP interface. BroadSoft does not validate qualitative aspects of the device or other device capabilities, which are outside the scope of the SIP signaling interface.

The validation covers the Yealink version(s) and BroadWorks release listed below. Other releases tested previously are documented in the PCG.

Yealink SIP-T12 version 5.50.0.10 Yealink SIP-T20 version 9.50.0.10 Yealink SIP-T22 version 7.50.0.10 Yealink SIP-T26 version 6.50.0.10 Yealink SIP-T28 version 2.50.0.10 Yealink SIP-T80 version 8.50.0.10 BroadWorks Release 17.0

\*This validation also applies to all subsequent maintenance releases to this device version.

Thanks,

David Block

Director, Technical Product Management +1.240.364.5118 dave@broadsoft.com