



March 12, 2003

Ron Wong
Widcomm
9645 Scranton Road #205
San Diego, Ca 92121

Ron Wong,

Due to certain Microsoft Windows Logo Program requirements that the following product does not fully meet at the time of testing, the Logo is awarded a contingency basis for Windows 2000 and Windows XP for the lifetime of the product.

Product: **Widcomm Bluetooth Driver**

Please send a copy of this letter with the submission paperwork for this product line when you make your submission. When submitted for Logo qualification, the product must pass all Windows Hardware Quality Labs testing not related to the following issues.

ISSUE:

The driver listed above is failing the systems check logo test in WIN 2000 and WIN XP on the following driver files:

FRMUPGR.sys
BTWUSB.sys
BTAUDIO.sys
BTWNDIS.sys
BTPORT.sys
BTKRNL.sys
xx.oem.inf that corresponds to the driver files listed above.

RESOLUTION:

This is an acceptable failure for the check logo test on any driver files listed above for a system type submission. This contingency is valid for 120 days after a program is implemented to logo this type of driver.


If Widcomm agrees with the foregoing terms and conditions, please sign where indicated below. Two signed originals must also be sent to:

Windows Hardware Quality Labs
One Microsoft Way
Redmond, WA 98052-6399

Microsoft Corporation

Gordan Lacey

Name (print)



Name (signature)

WHQL Group Manager

Title


MAR 19 2003

GORDAN LACEY
Date **GROUP MANAGER, WHQL**
WINDOWS DIVISION

Widcomm

Ron Wong

Name (print)



Name (signature)

DIRECTOR, PRODUCT MARKETING

Title

MARCH 12 2003

Date