



Release Notes

BTW 5.0.1.3300

September 01, 2006

Confidential and Proprietary Information

© Broadcom Corp., 2004, All rights reserved.
Printed in United States of America.
15435 Innovation Drive
San Diego, CA 92128
Phone: (858) 385-8800
Fax: (858) 385-8810

LICENSED SOFTWARE

© Copyright 2004, Broadcom® Corporation ("Broadcom"). All rights reserved.

WARNING:

This software and accompanying documentation are protected by copyright law and international treaties. Unauthorized reproduction or distribution of this software, or any portion of it, may result in severe civil and criminal penalties, and will be prosecuted to the maximum extent possible under the law.

Use of this software is governed by the terms of the end user license agreement that accompanies or is included with such software. Unless otherwise noted in the end user license agreement, or herein, no part of the documentation accompanying this software, whether provided in printed or electronic form may be reproduced in any form, or stored in a database or retrieval system, or transmitted in any form or by any means, or used to make any derivative work (such as translation, transformation, or adaptation) without the express, prior written consent of Broadcom.

Trademarks

Broadcom® and the pulse logo are trademarks of Broadcom Corporation and/or its subsidiaries in the United States and certain other countries. Microsoft® and Windows® are trademarks of Microsoft Corporation. Bluetooth® is a trademark of the Bluetooth SIG. Any other trademarks mentioned are the property of their respective owners.

BTW 5.0.1.3300

BLTH00070250

Other

Send To function cause error message in Outlook Express contact

Release Note:

Fixed buffer overflow.

BLTH00070513

Other

Merge Cr <scm-bmt-autobuilder>

Release Note:

Merge Cr
