

## **Acer DX900 Patch (Fix Empty SPN) Update Notification**

### **Fix and Improvement**

When using Vodafone SIM card in SIM2, the operator name is empty

### **Required File:**

Patch\_DX9RIL2\_FixEmptySPN.CAB

### **General Installation Steps:**

- Copy the file into your device.
- Double click the file and follow the on-screen instruction.
- When the installation complete, please reset the device.